

KEPHIS MOTOR VEHICLE ACCIDENT DATA FOR FY 2023/2024

DATE	REG NO.	DRIVER	LOCATION OF ACCIDENT	DAMAGE /REPAIR	TOWING COST	EXCESS	COST OF REPAIR	REMARKS
1 15/6/2023	KBG 013C	ROSE GICHIMU	Nakuru Lanet	Damaged front bumper,Grill, bumper bar and head lights, Door ssembly and radiator Repaired at Victoria garage in Nakauru	0		253,390	Paid by Insurance
2 21/6/2023	KBT 947N	ROBERT OBUNDE	NAIVASHA	Front bumper damaged, Fog lamb and stone guard damaged . Reaired at Garissa auto tune	0	0	92,800	Paid by Insurance
3 23/06/2023	KBN 585E	JOSEPH MUMO	JKIA	Damaged Rear bumper repaired at Garissa Auto tune	0		61,480	Paid by Insurance
4 8/7/2023	KAR 547L	C JISII	NAIROBI	Damaged rear bumper and win Damaged rear L/H/S bumper	0			Paid by Insurance
5 20/12/2023	KCP 475K	ROBERT ANDAKI	KITALE	Tail gate light and wing. Damaged LHS Bumper bracket, Rear bumper bar and Top bar plastic . Repaired at Prime Auto solutions Motors	0	0	20,300	Paid by Insurance
6 28/1/2024	KCP 613K	CHRISPINUS WAFULA	NAIVASHA	Damaged Front Bumper,Bonnet lid, Lower bumper support,Radiator panel.L/H/S side control arm Repaired at KCI garage.	0	0	153,816.00	Paid by insurance
7 1/24/2024	KBG 016C	ANTHONY MRIRANJA	MOMBASA	Damaged LHS Bumper bracket, Rear bumper bar and Top bar plastic . Repaired at Ryce Motors	0	0	563,412	Paid by insurance
8 18/5/2024	KCP 442K	KENNEDY NYAMWEYA	KISII	Damaged front hood assembly , Fender, front bumper, RH side headlamp,Radiator reflector, Grill and nudge bar. Repaired at Central farmers garage				Awaiting approval for repairs
9 14/06/2024	KCD 435G	ALEX NDIEMA	KITALE	Damaged front hood assembly , Fender, front bumper, RH side headlamp,Radiator reflector, Grill and nudge bar. Vehcile still under repaire at Autospin garage in Nyeri	0	0	388,136	To be paid by insurance
10 30/8/2024	KAV 252E	WILFRED ICHOHO	KIRINYAGA		0	0	1,597,714	
					TOTAL			